


Rodoirs pour trous borgnes avec liant métallique  
*Hones for blind bores with bronze bond*  
 Honahlen für Sacklochbohrungen mit Bronzebindung



∅	L1	L2	E	T	n	B	A	D	X	L <sub>max</sub>
2.00	50	40	0.8	11	4	---	---	7 - 150	0.05	35
2.50	50	40	0.8	11	4	---	---	7 - 150	0.05	35
3.00	50	40	1	11	4	---	---	7 - 150	0.05	35
3.50	50	40	1	11	4	---	---	7 - 150	0.05	35
4.00	55	45	1.5	11	4	---	---	7 - 150	0.05	40
4.50	55	45	1.5	11	4	---	---	7 - 150	0.05	40
5.00	70	55	2	11	4	---	---	7 - 200	0.05	50
6.00	75	60	1.5	11	6	---	---	7 - 200	0.05	55
7.00	75	60	1.5	11	6	---	---	7 - 200	0.05	55
8.00	80	65	2	11	6	---	---	7 - 200	0.05	60
9.00	80	65	2	11	6	---	---	7 - 200	0.05	60
10.00	85	70	3	16	6	---	---	7 - 200	0.05	65
11.00	110	75	3	16	6	---	---	7 - 200	0.05	70
12.00	110	75	3	16	6	---	---	7 - 200	0.05	70
13.00	110	75	3	16	6	---	---	7 - 200	0.05	70
14.00	110	75	4	21	6	---	---	7 - 200	0.05	70
15.00	115	80	4	21	6	---	---	7 - 200	0.05	75
16.00	115	80	5	21	6	---	---	7 - 200	0.05	75
17.00	115	80	5	21	6	---	---	7 - 200	0.05	75
18.00	120	85	5	21	6	---	---	7 - 200	0.05	80
19.00	120	85	5	21	6	---	---	7 - 200	0.05	80
20.00	120	85	6	21	6	---	---	7 - 200	0.05	80

1000

∅ 2.00 - 20.00

